

Information note

N° 10531AERRA

Dear customer,

With this Infineon Technologies AG information note, we would like to inform you about the following

Errata update affecting dedicated TRAVEO products

Infineon Technologies AG

Postal address D-81726 München Internet www.infineon.com Headquarters Am Campeon 1-15, D-85579 Neubiberg Phone +49 (0)89 234-0
Chairman of the Supervisory Board Dr. Herbert Diess
Management Board Jochen Hanebeck (CEO), Elke Reichart, Dr. Sven Schneider, Andreas Urschitz, Dr. Rutger Wijburg
Registered office Neubiberg Commercial register Amtsgericht München HRB 126492

Information note

N° 10531AERRA

- Products affected

Please refer to attached affected product list
INF_10531AERRA_[customer-no].pdf

- Detailed change information

Subject Errata update affecting dedicated TRAVEO products

Reason Update of Errata sheets

Description

<u>Old</u>	<u>New</u>
- CYT2B6 D errata rev1.9	- CYT2B6 D errata rev2.0
- CYT6BJ A errata rev1.2	- CYT6BJ A errata rev1.3
- CYT2B7 D errata rev2.2	- CYT2B7 D errata rev2.3
- CYT2BL A errata rev2.0	- CYT2BL A errata rev2.1
- CYT4BF D errata rev2.2	- CYT4BF D errata rev2.3
- CYT3BB_4BB B errata rev2.2	- CYT3BB_4BB B errata rev2.3
- CYT4DN B errata rev2.5	- CYT4DN B errata rev2.6
- CYT4DN A errata rev3.0	- CYT4DN A errata rev3.1
- CYT2CL A errata rev2.0	- CYT2CL A errata rev2.1
- CYT4DN C errata rev2.1	- CYT4DN C errata rev2.2
- CYT4EN A errata rev1.6	- CYT4EN A errata rev1.7
- CYT3DL A errata rev2.7	- CYT3DL A errata rev2.8
- CYT3DL B errata rev2.3	- CYT3DL B errata rev2.4
- CYT2B9 C errata rev2.3	- CYT2B9 C errata rev2.4

- Product identification

Not applicable (no change of product)

- Impact of change

Assessment in application required!

Information note

N° 10531AERRA

- Attachments

INF_10531AERRA_[customer-no].pdf affected product list

MyICP Links:

- CYT2B6 D errata rev2.0

https://myicp.infineon.com/sites/TRAVEODocumentation/Lists/defaultdoclib/Traveo%20II/Traveo%20II%20Body/Errata/CYT2B6_D_errata_rev2.0.pdf

- CYT6BJ A errata rev1.3

https://myicp.infineon.com/sites/TRAVEODocumentation/Lists/defaultdoclib/Traveo%20II/Traveo%20II%20Body/Errata/CYT6BJ_A_errata_rev1.3.pdf

- CYT2B7 D errata rev2.3

https://myicp.infineon.com/sites/TRAVEODocumentation/Lists/defaultdoclib/Traveo%20II/Traveo%20II%20Body/Errata/CYT2B7_D_errata_rev2.3.pdf

- CYT2BL A errata rev2.1

https://myicp.infineon.com/sites/TRAVEODocumentation/Lists/defaultdoclib/Traveo%20II/Traveo%20II%20Body/Errata/CYT2BL_A_errata_rev2.1.pdf

- CYT4BF D errata rev2.3

https://myicp.infineon.com/sites/TRAVEODocumentation/Lists/defaultdoclib/Traveo%20II/Traveo%20II%20Body/Errata/CYT4BF_D_errata_rev2.3.pdf

- CYT3BB_4BB B errata rev2.3

https://myicp.infineon.com/sites/TRAVEODocumentation/Lists/defaultdoclib/Traveo%20II/Traveo%20II%20Body/Errata/CYT3BB_4BB_B_errata_rev2.3.pdf

- CYT4DN B errata rev2.6

https://myicp.infineon.com/sites/TRAVEODocumentation/Lists/defaultdoclib/Traveo%20II/Traveo%20II%20Cluster/Errata/CYT4DN_B_errata_rev2.6.pdf

- CYT4DN A errata rev3.1

https://myicp.infineon.com/sites/TRAVEODocumentation/Lists/defaultdoclib/Traveo%20II/Traveo%20II%20Cluster/Errata/CYT4DN_A_errata_rev3.1.pdf

Information note

N° 10531AERRA

- CYT2CL A errata rev2.1
https://myicp.infineon.com/sites/TRAVEODocumentation/Lists/defaultdoelib/Traveo%20II/Traveo%20II%20Cluster/Errata/CYT2CL_A_errata_rev2.1.pdf
- CYT4DN C errata rev2.2
https://myicp.infineon.com/sites/TRAVEODocumentation/Lists/defaultdoelib/Traveo%20II/Traveo%20II%20Cluster/Errata/CYT4DN_C_errata_rev2.2.pdf
- CYT4EN A errata rev1.7
https://myicp.infineon.com/sites/TRAVEODocumentation/Lists/defaultdoelib/Traveo%20II/Traveo%20II%20Cluster/Errata/CYT4EN_A_errata_rev1.7.pdf
- CYT3DL A errata rev2.8
https://myicp.infineon.com/sites/TRAVEODocumentation/Lists/defaultdoelib/Traveo%20II/Traveo%20II%20Cluster/Errata/CYT3DL_A_errata_rev2.8.pdf
- CYT3DL B errata rev2.4
https://myicp.infineon.com/sites/TRAVEODocumentation/Lists/defaultdoelib/Traveo%20II/Traveo%20II%20Cluster/Errata/CYT3DL_B_errata_rev2.4.pdf
- CYT2B9 C errata rev2.4
https://myicp.infineon.com/sites/TRAVEODocumentation/Lists/defaultdoelib/Traveo%20II/Traveo%20II%20Body/Errata/CYT2B9_C_errata_rev2.4.pdf

In case you don't have access, please contact your local Sales/ FAE.

- **Intended start of delivery**

Not applicable

If you have any questions, please do not hesitate to contact your local sales office.